

Republic of the Philippines PARTIDO DEVELOPMENT ADMINISTRATION

Created Under R.A. 7820 Tigaon, Camarines Sur

20
, 20

PRICE QUOTATION

	quote your prices of the following articles which this			rchase for u	use in <u>repair</u>
and m	PARTICULARS	QTY.	UNIT	UNIT	TOTAL COST
	PARTS: Plunger and barrel Cam face assy Overhaul gasket Banjo bolt w/ check valve Banjo bolt w/ strainer Solenoid Air filter Radiator assy LABOR: 1. Repair/overhaul of mechanical speed governor 2. Replace air filter & radiator assy.	6 1 1 1 1 1 1 1	Pcs. Pcs. Set Pcs. Pcs. Pcs. Pcs. Pcs. Iot		
Contac Canvas Sir/Mad	AT#: s: one No.: t Person: sser:			after each i	

PDA-F-PROC/PQ-01 Rev. No. 0 September 1, 2015